

Rio3224-D/Rio1608-D Firmware V1.14 Release Notes

Caution

- The [PREVIEW] key and Help functions will be available in future updates.
- Integrated function with Nuendo Live works only with the CL CONSOLE that is set to ID#1.
- When multiple PCs running DVS are connected, the CL CONSOLE will only integrate with Nuendo Live on the PC which has the lowest RACK No. on the CL CONSOLE.
- You need to update the Dante-MY16-AUD firmware to V3.3.9 or later before using the Dante-MY16-AUD with the CL series firmware **V1.14**.

V1.14 Release Firmware

MAIN	SUB	DANTE
1.14	1.14	3.6.4.7 – 3.4.2.1 – 1.0.8

V1.14

Fixed bug

- Solved a problem in which operation would become unstable if multiple Dante devices were connected in the Dante Network.

Known issues

- If the Dante Virtual Soundcard (DVS) is patched to the CL series device using the Dante Controller, the patching may not be recalled correctly when the CL series device is restarted. Patch the DVS again.
- In an environment with two or more CL series devices, the following malfunctions may have occurred with the I/O RACK OUTPUT PATCH pop-up window.
 - A port patched to a different CL series device could not be canceled, but a message would appear, indicating that the port could be canceled.

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

(C) 2012 Yamaha Corporation All Rights Reserved.